







Date: Monday, 16/07/2007 3:49:17 PM
User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : REWORK
Job Number : 33572	
Estimate Number : 10804	
P.O. Number : N/A	Part Number : D2803041
This Issue : 16/07/2007 S.O. No. : N/A	Drawing Number : D2803041
Prsht Rev. : NC	Project Number : N/A
First Issue : N/A Type : MACHINED PARTS	Drawing Revision : N/A
Previous Run : 00015	Material : N/A
Written By : <u>U</u>	Due Date : 23/07/2007
Checked & Approved By : <u>U</u>	Qty: 1 Um: Each
Comment :	

Additional Product

Job Number: 

Seq. #:	Machine Or Operation:	Description :
1.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
		
	Comment: SMALL & MEDIUM FAB RESOURCE 1 PRESS STOP D2805-1 B <u>29403</u>	
2.0	D28051	Stop
		
	Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Stop	
3.0	QC5	INSPECT WORK TO CURRENT STEP
		
	Comment: INSPECT WORK TO CURRENT STEP	

Job Completion 

*See
w/o 29403*

U 07-07-17

QC 21 - 07.07.17